

Tachometer

For fast mechanical measurements of RPM and frequency on small motors and engines



- **Simple and Easy to use**
- **Range 2.000 - 21.000 RPM**
- **Range 35 - 350 Hz**
- **No Batteries**
- **Work with Resonance**
- **Made of Aluminium**

Sirometer

For accurate and fast measurements of RPM and frequency Hz on all kinds of motors and engines



- **Simple and Easy to use**
- **Range 800 - 50.000 RPM**
- **Range 14 - 800 Hz**
- **No Batteries**
- **Work with Resonance**
- **Tolerance 1-2%**



The Sirometer is delivered with a protective sleeve



The Tachometer is delivered with a protective sleeve